

FORM-A-TREAD®

SUPERIOR SAFETY, TRACTION & VISIBILITY

TRIPPING HAZARD – STAIRWAY ENTRY

High Profile Museum, Pittsburgh, PA – June 2017

Client: Carnegie Institute

Site: The Carnegie Museum of Art & Natural History

Area Addressed: Forbes Ave Main Entrance

Problem: Poor Visibility Exterior Granite Steps

Product: Form-A-Tread, White

Days to Complete: 1

Replaced: Paints & Tapes



The Carnegie Museum of Arts & Natural History had a problem with poor visibility on its unique, granite exterior steps into the main entrance. Due to the color and design of the steps, it was hard for pedestrians to denote where steps started and ended, resulting in trips, slips and falls. Where paint, tape and other products failed due to poor adhesion to the stone and the high level of wear from foot traffic, strollers, UV rays and weather conditions, the problem was solved with Form-A-Tread which easily bonded to the surface of the stone.

After 2.5 years, the treads are showing no signs of wear because of Form-A-Tread's superior durability.



Form-A-Tread Company
Div. of RFG Materials Co. (LLC)
Phoenixville, Pennsylvania 19460
www.form-a-tread.com

We've spent years worrying about slips, trips and falls so you don't have to!