

FORM-A-TREAD®

SUPERIOR SAFETY, TRACTION & VISIBILITY

DETERIORATING HIGH-TRAFFIC VIP ENTRANCE: University Community Center, Miami, Florida – July 2019

Client: Florida International University

Site: The Graham Center

Area Addressed: Rear Access Ramp

Problem: Deteriorating/ Unsafe/ Unsightly

Product: Form-A-Tread® SL (Self-Leveling), Grey


Days to Complete: 1

Replaced: Grit Paint



The Graham Center at FIU has an access ramp at the rear of the building adjacent to the loading dock. This access is used frequently and is the point of entry for VIP's. This ramp was deteriorating and needed to be refurbished. FIU chose Form-A-Tread® SL as the solution for refurbishing the ramp and providing a safe and attractive, non-skid surface. The ramp surface was prepared for treatment, then Form-A-Tread® SL with grey aggregate was applied, adding extra, durable traction. Curing time was 3 hours. The ramp was accessible the next day

Form-A-Tread was able to repair and provide a sustainable solution to a deteriorating ramp in just 1 day!



Form-A-Tread Company
Div. of RFG Materials Co. (LLC)
Phoenixville, Pennsylvania 19460
www.form-a-tread.com

We've spent years worrying about slips, trips and falls so you don't have to!